

**SERVICE BULLETIN INDEX  
AA-1 AND AA-5 SERIES AND AG-5B**

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
101	25 October 1968	Wheel Fairing Improvements (OBSOLETE) See Service Letter 70-3	
102	31 October 1968	Canopy Improvements (OBSOLETE) See Service Letter 70-4	
103	21 November 1968	Seat Belt Chafe Protection (INACTIVE)	
104A	9 December 1968	Wheel Fairing Removal (OBSOLETE) See Service Letter 70-3	
105	3 January 1969	Static Line Chafing (INACTIVE)	
106	7 January 1969	Ground Strap Installation (INACTIVE)	
107	29 January 1969	Brake System Cleaning (OBSOLETE) See Service Bulletin 109	
108	20 February 1969	Nose Gear Strut Replacement (OBSOLETE) All A/C complied with	
109	27 February 1969	Brake System Retrofit (OBSOLETE) All A/C complied with	
110	27 February 1969	Nose Gear Improvements (OBSOLETE) All A/C complied with	
111	31 March 1969	Throttle Arm Inspection (OBSOLETE) See Service Bulletin 112A	
112A	2 April 1969	Throttle Arm Inspection (INACTIVE)	
<hr/>			
113	28 May 1969	Engine Cooling Improvements Reference SESK 105	AA1-0001 thru 0108 & 0110 thru 0115
114A	17 November 1969	Required Inspection of the Drain Plugs in Marvel-Schebler Carburetors For Excessive Thread Lubricant (Reference AD 69-24-3)	AA1-0001 thru AA1-0205 Reference SB for specific instructions
115	15 December 1969	Main Gear Bracket Inspection Reference SK 108	AA1-0002 thru 0008 & 0011 thru 0014

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
116	9 January 1970	Exhaust System Inspection Supersedes Service Letter 69-6 (Reference AD 70-5-5)	AA1-0001 thru 0159
117	11 May 1970	Paint Removers	All Models, All Serials AA1, AA1A, AA1B AA1C, AA5, AA5A AA5B
118	28 July 1970	Oil Pressure Line Inspection & Elbow Installation	AA1-0001 thru 0436
119 Suppl.	18 September 1970 15 October 1970	Spinner/Back Plate Inspection	AA1-0001 thru AA1-0416
120	7 October 1970	Throttle Control Inspection	AA1-0001 thru 0436 & All Spares Stock of P/N 507002-1 & 507002-2 Throttle Control
(121) 121A	8 January 1971	Nose Gear Strut Inspection (Reference AD 71-4-3)	AA1-0001 thru 0432 & All Spares Stock of P/N 702057-501 & 702057-503 Strut Assemblies Shipped from the factory before 1 July 1970
122	1 February 1971	Wire Bulletin-Muffler Weldment failure. (OBSOLETE) Superseded by Service Letter 71-3	See Service Letter 71-3
123	24 February 1971	Carburetor Inspection	AA1-0123 thru AA1-0426; AA1a-0001 thru AA1A-0027
124	3 September 1971	Wire Bulletin-Modification of 902026-1 Rear Radio Supports	AA1A-0141, 0149 0152, 0153, 0159 0188 & 0203
125	9 November 1971	Weight & Balance Data Sheet Correction	AA1A-0001 thru 0260
126	18 January 1972	Control Surface Bearing Support Inspection	AA1A-0095 thru AA1A-0323
127A	19 July 1974	Control Cable Inspection (Reference AD 72-06-02)	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0049 AA5-0001 thru 0209

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
128	23 February 1972	Fuel Tank Vent Line Inspection & Modification. Supersedes Wire Bulletin 128	AA5-0002 thru 0045
129	29 March 1972	Front Seat Improvements. Supersedes Wire Bulletin 129 (Reference Service Kit 114)	AA5-0001 thru 0089
130	8 March 1972	Flap Motor / Right Rudder Cable Clearance Inspection	AA1-0001 thru AA1-0459; AA1A-0001 thru AA1A-0470
131	3 May 1972	Rudder System Spring Replacement (OBSOLETE) See Service Manual	All Model AA-1, AA-1A & AA-5
132	19 September 1972	Additional Aileron Drain Holes	AA5-0001 thru 0159
133	13 October 1972	Wire Bulletin – Fuel Pressure Fitting Inspection	AA1A-0414 thru 0470 AA1B-0001 thru 0031 AA5-0084 thru 0204
133	16 October 1972	Fuel Pressure Lines Inspection Supersedes Wire Bulletin 133	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA5-0001 thru 0405
134	21 December 1972	Headliner Inspection & Replacement (Reference Service Kit 122A, 123A & 124)	AA1-0001 thru 0459 AA1A-0001 thru 0420 AA1B-0001 thru 0061 AA5-0001 thru AA5-0240
135	20 February 1973	Carburetor Air Box Modification	AA5-0001 thru 0300
136	20 February 1973	Elevator Trim Tab Hinge Inspection	AA5-0001 thru 0284
137A	22 June 1973	Engine Mount Inspection, Supersedes Service Bulletin 137	AA5-0175 thru 0290
138	7 June 1973	Placard Installation (Reference AD 73-13-07)	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0177
139	5 December 1973	Master Cylinder Inspection	AA1B-0230 thru 0246 0248 thru 0252, 0254 0260, 0268 AA5A-0410 thru 0423 0430
140	14 December 1973	ELT Antenna Rivet Change	AA1A-0330 thru 0470 AA1B-thru 0325 AA5-0001 thru 0491

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
141	15 January 1974	Left-Hand Magneto "P" Lead Replacement	AA1B-0278 thru 0313 AA5-0438 thru 0482
142	20 June 1974	Throttle Cable Housing Wear Reference Service Kit 130 SK 130-1, SK 130-2	AA1-0348, 0433 thru 0459, AA1A-0001 thru 0470, AA1B-0001 thru 0514, AA5-0001 thru 0714
143	5 December 1974	United Altimeter (Reference AD 74-24-13)	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0486 AA5-0001 thru 0680
144A	12 March 1975	Mixture Control, Supersedes Service Bulletin 144 (Reference AD 75-09-07)	AA1-0001 thru 0459 AA1B-0001 thru 0470 AA1A-0001 THRU 0470
145	29 January 1975	Wire Bulletin – AA-5B Upper Engine Mount Bolt Inspection	AA5B-0003 thru 0005 0007 thru 0011, 0013 thru 0015
146	5 February 1975	Firewall Rivet Installation	All Model AA-1 & AA-1A, AA1B-0001 thru 0502 & AA5-0001 thru 0710
147	18 February 1975	Wire Bulletin – Rudder Control Bar Inspection (Reference AD 75-07-04)	All Model AA-1 AA-1A, AA-1B, AA-5 & AA-5B Aircraft Delivered Prior to February 18, 1975
148	25 February 1975	Wire Bulletin – Mandatory Induction Air Filter Replacement	AA5B-0002 thru 0023
149	3 March 1975	Nose Gear Strut Inspection and Protection	AA1-0001 thru 0459 AA1A-001 thru 0470 AA1B-0001 thru 0497 AA5-0001 thru 0697 AA5B-0001 thru 0013
(150) 150A	12 January 1976	Carburetor Mixture Control Replacement. Supersedes Service Bulletin 150 (Reference AD 76-04-05)	AA5B-0001 thru 0215

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
151	23 October 1975	Center Spar Console Inspection and Modification	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0538 AA5-0001 thru 0834 AA5A-0001 thru 0057 AA5B-0001 thru 0180
152A	22 January 1976	Upper Cowl Center Hinge Replacement. Supersedes Service Bulletin 152 (Reference 76-01-02)	AA5-0641 thru 0834 AA5A-0001 thru 0056 AA5B-0001 thru 0183
153	2 February 1976	Spar / Skin Spacer Removal	AA5A-0001 thru 0107 AA5B-0001 thru 0238
154	9 April 1976	Fuel Line Inspection	AA5A-0001 thru 0124 having Optional Long Range Fuel Tanks & AA5B-0001 thru 0238
155	30 July 1976	Bondline Protection (Reference SESK 125) (Reference AD 76-17-03)	AA-1, AA1A-0001 & Sub, AA1B-0001 thru 0641, AA5-0001 & Sub AA5A-0001 thru 0173 0176, thru 0196 AA5B-0001 thru 0309 & 0311 thru 0324
156	11 October 1976	Oil Cooler Replacement (Reference AD 76-22-09)	AA5A-0001 thru 0227 AA5B-0001 thru 0359
157	12 November 1976	Wire Bulletin – Control Wheel Shaft and Bearing Inspection (Amendment 1 Revises Serial Numbers)	AA1B-0238 thru 0676 AA5-0406 thru 0834 AA5A-0001 thru 0258 AA5B-0001 thru 0390
158	14 June 1977	Bondline Protection Vertical Stabilizer, Rudder	AA5A-0146 thru 0330 AA5B-0282 thru 0460
159	25 February 1977	Carburetor Heat Valve Inspection / Replacement (Reference AD 77-07-04)	AA5-0641 thru 0834 AA5A-0001 thru 0321
*	4 April 1977	Price Catalog Revision #1-77	

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
(160) 160	21 March 1977	Alternate Static Valve Inspection and Cleaning (Reference 77-08-03)	AA5A-0001 thru 0340 & AA5B-0001 thru 0451 Aircraft Equipped with an Alternate Static Source System. All Other Aircraft that have been modified by the addition of Gerdes A-1390 Valve. All Gerdes A-1390 Valves shipped from GAAC prior to March 19, 1977.
161	24 May 1977	NARCO Service Bulletin ELT-10 No. 7, ELT-10 Inspection for corrosion (NARCO Avionics Service Bulletin ELT-10 No. 7 Attached)	All GAAC Aircraft equipped with NARCO ELT-10
162	28 February 1979	Removal of Canopy Cable System	AA1B-0551 thru 0680 AA1C-0001 thru 0211
163	28 May 1979	Aileron Torque Tube Inspection and Modification	AA5A-0176 thru 0805 AA5B-0302 thru 1078
164	1 June 1979	Rockwell-Collins Service Bulletin No. 5-Audio Marker Receiver – to - Transponder Interference	All Model AA-5A & AA-5B Aircraft equipped with Collins AMR-350 Audio/Marker Panels
165A	9 November 1979	Aileron Inspection or Modification (Reference AD 79-22-04 & 79-16-05)	AA5-0001 thru 0834 AA5A-0001 thru 0899 AA5B-0001 thru 1325
166	1 October 1979	Seat Belt Replacement (Reference AD 79-16-02)	AA1B-0472 thru 0680 AA1C-0001 thru 0211 AA5-0808 thru 0834 AA5A-0001 thru 0643 AA5B-0075 thru 0860
167B	19 October 1981	McCauley Propeller Hub Inspection	
167C	12 May 1983	McCauley Propeller Hub Inspection (Reference AD SESK 143)	All AA5B equipped with McCauley Prop Model 1A170 / FFA 7563

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
168	29 January 1980	Aileron Torque Tube Joint Inspection (Reference AD 79-16-05, AD 79-22-04)	All Model AA-5A & AA-5B Aircraft equipped with Service Kit 150 Modified Ailerons. All AA-5 Aircraft equipped with Service Kit 150 Modified Aileron & the 5202035-505 Aileron Torque Tube Assembly
169	18 March 1980	Outboard Elevator Drain Holes	AA5A-0001 thru 0896 AA5-B-0001 thru 1310
170	23 July 1981	Air Filter Retention Screen (Reference AD 81-24-03, SESL 81-1, SESL 77-4)	AA5A-0641 thru 0834 AA5A-0001 thru 0900
171	3 June 1981	Voltage Regulator Replacement	AA5-0603 thru 0834 AA5A-0001 thru 0899 AA5B-0001 thru 1325
172	Not Used		
173	11 March 1985	Seat Bracket Replacement (Reference AD 85-21-02)	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0680 AA1C-0001 thru 0211
174	26 June 1987	Inspection of Carburetor Heat Butterfly Valve	AA1-0001 thru 0459 AA1A-0001 thru 0470 AA1B-0001 thru 0680 AA1C-0001 thru 0211
175	26 June 1987	Inspection of Carburetor Inlet Duct	AA5-0641 thru 0834 AA5A-0001 thru 0899
176	26 July 1989	Integral Fuel Tanks, Inspection for Deteriorated Access Cover Sealant and Fuel System Contamination (Reference AD 89-18-08)	AA5-0001 thru 0834 AA5A-0001 thru 0899 AA5B-0001 thru 1325
*		Western Union-Throttle Cable Brackett	
176	5 April 1991	Alternator Light Circuit Modification	99998,10000 thru 10033
177	11 September 1991	Inspection of Aileron Torque Tubes	AG-5B 99998 & 10000-10073, All AA-5, AA-5A, AA-5B & AG-5B Aircraft

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B

<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
178	23 January 1992	Inspection of Nose Landing Gear Torque Tubes	AG-5B 99998 & 10000-10115, AG-5B 99998 & 10000-10097
178A	30 June 1993	Inspection of Nose Landing Gear Torque Tubes	AG-5B 99998 & 10000-10097
179	25 September 1992	Flap Torque Tube Bearing Assembly	AG-5B 99998 & AG-5B 10000 & subsequent, AA-5 0001 & subsequent, AA-5A 0001 & subsequent, AA-5B 0001 & subsequent
180	10 March 1993	Fuel System Inspection	AG-5B 99998, AG-5B 10000 THRU 10130
181	18 November 1992	Fuel System Contamination	AG-5B 99998, AG-5B 10000 thru AG-5B 10006
182	10 March 1993	ARTEX-H4K Emergency Locator Transmitter Model 110-4	AG-5B 99998; AG-5B 10000 thru AG-5B 10019
183	29 June 1993	Parker Hannifin Wheel & Brake "Master Cylinders"	AG-5B 99998, 10000 thru 10151
184	10 July 1993	Aileron Control Interference	AG-5B 99998 & 10000 thru 10158
185	30 September 1993	Wing Attach Shoulder Bolts	AA5-0001 & subsequent AA5A-0001 & subsequent AA5B-0001 & subsequent AG-5B 99998, 10000 10174 (SUPERCEDED)
185A	10 January 2005	Wing Attach Shoulder Bolts	AA5-0001 & subsequent AA5A-0001 & subsequent AA5B-0001 & subsequent AG-5B 99998, 10000 thru 10174
369G	7 September 1987	Engine Inspection After Over-speed or Over-boost	All AVCO Lycoming piston engines
189	16 September 2002	Missing Rivets	AG-5B 99998, 10000 THRU 10174
190	01 March 2005	Throttle Cable	AG-5B 99998, 10000 thru 10174 and 10201 thru 10246

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B



<b>SB#</b>	<b>DATE</b>	<b>TITLE</b>	<b>EFFECTIVITY</b>
191	01 April 2005	Rear Seat Belt Attach Bracket	AG-5B 10000 thru 10174 and 99998
192	20 August 2009	Aft Fuselage Inspection	AA5-0001 & subsequent
193	5 November 2010	Wing Spar Corrosion	AG-5B All Serial Numbers
194	1 August 2011	Control Column Bearing Lubrication	AG-5B 10201 - 10251

3/21/2012

Service Bulletin Index  
AA-1, AA-5 Series and AG-5B